

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BI307
SE
1/4-1/2
0.461 mi.
2436 ft.
CON ED
2942 W 5TH ST
BROOKLYN, NY 11224
Site 1 of 3 in cluster BI

NY Spills
NY MANIFEST
S112227339
N/A

Relative:
Higher

Actual:
4 ft.

SPILLS:

Name: OUTSIDE PARKING LOT
Address: 2942 WEST 5TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1206910 / 2013-02-14
Facility ID: 1206910
Facility Type: ER
DER Facility ID: 424241
Site ID: 469936
DEC Region: 2
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 2401
Spill Date: 2012-10-13
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 2012-10-13
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-10-13
Spill Record Last Update: 2013-02-14
Spiller Name: ANTHONY LARA
Spiller Company: UNKOWN
Spiller Address: 2942 WEST 5TH STREET
Spiller Company: 999
Contact Name: ANTHONY LARA
DEC Memo: "10/14/12-Zhune responded to this site. Riteway was doing the cleanup. Spoke to the superintendent(Joe Thamson 718-946-4964). He said the boiler turn off due to mechanical failure. Oil came by the vent pipe. Approximate 50 to 100 gallons of oil spilled. Some oil run onto the lawn between the tank house and the parking lot. Some went to the parking lot and then to a drain located in the parking lot. The NYC DEP Water and Sewer operation crew confirmed that oil went to a manhole located in front of the impacted area. This manhole is connected to the storm sewer that runs along West 5 Street and then changes direction to Neptune Ave. and then exits to the outfall at Conney Island creek. Riteway set up absorbent booms at the end of the line (Outfall). At 7PM P.Officer Kyles was inspected the area at the Conney Island Creek. He said that he found no verifiable impacted waterbody. No sheen. 10/22/12- Zhune visited the site. Spoke to Carlos(Maintenance Director). Approved left two areas of grass with contamination. Endpoint Soil Samples were collected from the dirt planter. Carlos called approved and asked them to comeback and complete the cleanup. 02/14/13- Riteway sent the report dated 01/15/13. Aproved oil Company contacted Riteway Tank maintenance Corp. on the 13th of October 2012 to address an overfill of fuel oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

storage tank. The tank was overfilled. Approximately 100 gallons #2 fuel oil escaped through the vent line, spilled into a dirt planter and migrated underneath the black top in a parking area. An area approximately 154 square feet an approximately 30 deep was excavated. During the excavation, the soil was continuously field screened via PID. The entire affected area was remediated until free from contamination. Five clean endpoint samples were retrieved at a depht of 30 from North, South, East, West and Center of the eacavation and sent to a certified lab. The soil analytical results are within acceptable limits. Spill Closed "

Remarks:

"Transferring fuel from tank to tank - spilled - clean up pending"

All Materials:

Site ID: 469936
Operable Unit ID: 1219814
Operable Unit: 01
Material ID: 2218359
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum

Quantity: 100.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

NY MANIFEST:

Name: CON ED
Address: 2942 W 5TH ST
City,State,Zip: BROOKLYN, NY 11224
Country: USA
EPA ID: NYP004768073
Facility Status: Not reported
Location Address 1: 2942 W 5 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11224
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004768073
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

| | |
|---------------------------------|--|
| seq: | Not reported |
| Year: | 2015 |
| Trans1 State ID: | NJ0000027193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 04/14/2015 |
| Trans1 Recv Date: | 04/14/2015 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 04/17/2015 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004768073 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSD ID 1: | NJD002200046 |
| TSD ID 2: | Not reported |
| Manifest Tracking Number: | 014085019JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 4000 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | D008 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |